

## **Changes from System Version 1.0.2**

### **General**

#### **[Improvement]**

The behavior of the Half Damper and Re-damper functions have been addressed and improved for the acoustic piano programs that use the XL bank's PCM.

#### **[Fix]**

Occasionally, note-on messages from the keyboard, internal sequencer and MIDI Input didn't generate sound. This has now been addressed.

#### **[Fix]**

Occasionally, when there was delay between a note-on message and sound output from the "Osc Delay" and/or "Timbre/Track Delay" functions, the Oscillator sounds would not be correct. This has now been addressed.

### **MIDI**

#### **[Fix]**

Occasionally when playing the keyboard, MIDI message transmission, such as note-on/off messages, could have been delayed. . This has now been addressed

### **Program mode**

#### **[Fix]**

Depending on the operation, the Multi-sample Start Offset parameter could have become unavailable (grayed-out) even when it should be available in valid cases. This has now been addressed.

### **Combination mode**

#### **[Fix]**

When selecting other programs or banks in the "Bank/Combination Select" dialog box on the P0:Play-Tone Adjust page, the dialog box could unintentionally close automatically without the OK/Cancel buttons being pressed. This has now been addressed.

### **Global mode**

#### **[Fix]**

When the Power-On Mode parameter was set to "Memorized" and the system started up on the P5: Drum Kit page, the [DRUM TRACK] button could have become temporary unavailable. This has now been addressed.

[Fix]

Receiving an Arpeggio Pattern data dump in the Arpeggio Pattern Edit page could have caused an operational error. This has now been addressed.

### **Media mode**

[Fix]

In the “Load an Arpeggio Pattern” menu command, pattern numbers higher than 256 could have been incorrectly displayed. This has now been addressed.

Various other minor operational enhancements are also included in this update.

## **Changes from System Version 1.0.1**

### **General**

[Fix]

When the Auto Power-Off function is active, operations using buttons and the TouchView display could become unavailable. This has now been adjusted.

[Fix]

Occasionally, the Drum Pattern numbers wouldn't match the number in the KROME Editor. This has now been adjusted.

### **MIDI**

[Fix]

Transmission of MIDI Time Clock has stopped when entering GLOBAL mode from Sequencer mode. This has now been adjusted.

### **Effect**

[Fix]

Effect # 108: Limiter – Cho/FIng may not function correctly depending on where it was placed and its parameter setup. This has now been adjusted.

[Fix]

On the IFX Routing page, the routing chart graphic might not have been displayed correctly. This has now been adjusted.

[Fix]

On the IFX Setup page, Pan, Bus and Send parameters may have unnecessarily become grayed-out and unavailable depending on the IFX chain setup. This has now been adjusted.

### **Program mode**

[Fix]

Edits using REALTIME CONTROL knobs, for example, envelope attack time, were not saved correctly by the Write Program procedure. This has now been adjusted.

[Fix]

When the Auto Song Setup function was used, MFX functions may not have initialized correctly. This has now been adjusted.

## **Sequencer mode**

[Improvement]

When copying a program's setting into a track by using the Copy From Program command without copying the ARP and Drum Track settings, the Song's tempo value has been reset to 120 unintentionally. Now, the original Song's tempo value is kept in.

[FixFix]

The process of editing IFX "Chain to" parameters may have occasionally caused an operational error. This has now been adjusted.

Various other minor operational enhancements are also included in this update.

## **Changes from System Version 1.0.0**

### **General**

[Improvement]

Version 1.0.1 adds many improvements, and additional support for the KROME Editor and Plug-In Editor software. Please update your KROME 61/73/88 to System Version 1.0.1 before using the KROME Editor and Plug-In Editor.

[Improvement]

Minor adjustments and improvements have been made for many Preload Programs and Combinations.

[FixFix]

The velocity meters that are displayed in various modes and pages sometimes inappropriately appeared yellow, which means “muted”, instead of blue, which means “active”. This has now been adjusted.

### **Effect**

[Fix]

The Wet/Dry parameter in Effect 054: Grain Shifter occasionally reset to “Dry” during when in use. This has now been adjusted.

[FixFix]

On the IFX Setup page, some editable parameters may have unnecessarily become grayed-out and unavailable. This has now been adjusted.

[Fix]

The FX Preset names may have temporarily included errors after executing the “Write FX Preset” page menu command. This has now been adjusted.

### **Program mode**

[Fix]

When selecting a multisample on the OSC1/2 Setup page, the Start Offset parameter did not update correctly. As the result, the actual sound did not match the Start Offset parameter setting. This has now been adjusted.

[Fix]

In the AMS Mix pages, when selecting the Mixer Type parameter, other parameters on this page (which vary per Mixer Type) may not have updated correctly. This has now been adjusted.

[Fix]

When editing the Multisample bank parameter via MIDI System Exclusive messages, a selection error could occur in that Multisample bank. This has now been adjusted.

## **Sequencer mode**

[Fix]

The “Load Template Song” page menu command could have occasionally caused an operational error. This has now been adjusted.

[Fix]

The Track View page may have temporarily shown inaccurate patterns. This has now been adjusted.

[Fix]

When putting patterns onto a MIDI track using the “Put To Track” page menu command that can be found on the Pattern Edit page, the pattern may not have been displayed correctly on the “Event Edit” page, etc. This has now been adjusted.

[Fix]

On the Track View page, the track display could have updated incorrectly depending on the settings of the “Time Scale” parameters. This has now been adjusted.

## **Global mode**

[Fix]

When loading a .PCG file, if the current MIDI Channel value is not identical to the value in the PCG file, sound could not be generated temporarily. This has now been adjusted.

[Improvement]

In the “Fixed Note Setup” dialog on the Arpeggiator pattern page, the procedure for ENTER + Key have been improved.

## **Media mode**

[Fix]

File names including “\_” (underscore) have been displayed incorrectly. This has now been adjusted.

[Improvement]

While loading M50-format .PCG files, the Drum Track Pattern conversion method has been improved.

Various other minor operational enhancements are also included in this update.